



FIG. 5








end from the first of the first work work in the first of the first of

He that the many count of the Head of the







FIG. 9A



11/19

FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D





FIG. 11E







FIG. 13



14/19

FIG. 14B




FIG. 15





FIG. 16



4 - Con 1


. ::

FIG. 17

| URL http://www.maintain.co.jp/db/input.html |
|--|
| TROUBLE DB INPUT WINDOW |
| |
| OCCURRENCE DATE 2000/3/15 4040 TYPE OF APPARATUS ********* 4010 |
| TYPE OF APPARATUS $\times \times \times$ |
| SUBJECT OPERATION ERROR (START-UP ERROR) ~ 4030 |
| SERIAL NUMBER S/N 465NS4580001 4020 |
| DEGREE OF URGENCY D ~4050 |
| SYMPTOM LED IS KEPT FLICKERING AFTER * 位 4060 |
| |
| REMEDY POWER ON AGAIN (PRESS RED BUTTON IN ACTIVATION) 4070 |
| PROGRESS INTERIM HAS BEEN DONE 4080 |
| |
| (SEND) (RESET) 4100 4110 4120 |
| LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE |

· · · ·

FIG. 18



11-19-14 1 1 2 2

FIG. 19

